



State of Utah
DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

Michael O. Leavitt
Governor


Ted Stewart
Executive Director

James W. Carter
Division Director

355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203
801-538-5340
801-359-3940 (Fax)
801-538-5319 (TDD)

May 3, 1996

TO: Minerals File

FROM: Lynn Kunzler, Reclamation Specialist 

RE: Site Inspection, Lanny Jensen, Cream Project Mine, S/039/009, Sanpete County, Utah

Date of Inspection: May 1, 1996
Time of Inspection: 1:00pm
Conditions: Partly cloudy
Participants: Lynn Kunzler, DOGM

Purpose of Inspection: Document site conditions

Lanny Jensen filed a Notice of Intention (SMO) for this site with the Division on February 23, 1996. Our review of February 26, 1996 indicated the Notice was not complete and requested a topo map showing access road(s) to the site. No variances were requested.

This quarry is accessed via a graveled county road south of the town of Mayfield. The quarry is adjacent to this county road. The USGS topo map shows the general location (as per township range and section) about 2.4 miles south of Mayfield. However, the quarry is about 3.5 miles south of town. The legal description needs to be verified.

No one was at the site during this inspection, however it was evident that the quarry was active due to equipment on site and several pallets of stone. About 2 acres have been disturbed. Of concern at this site is that apparently no topsoil has been salvaged and stockpiled. It appears that there was good topsoil where the 'work area' is located that should be saved for reclamation.

Attempts to call Mr. Jensen found that his phone (# provided with the NOI) is not in service and Directory Service has no listing for a Lanny Jensen in Richfield.

cc: Lanny Jensen
s039009.ins

